



MARITIME LLOYD

34 A, Off.3, Dimitry Tavadzebuli Str, Batumi 6000, Georgia

Tel: + 995 422 277537 ; Fax: + 995 422 277536.

E-mail: stat@geolloyd.com www.geolloyd.com

Circular No: 07 / 25.06.2014

To :	Maritime Lloyd Authorized Surveyors
Dated:	25.06.2014
Subject:	Revision of Maritime Lloyd's Technical Working Procedures as per IMO Res. MSC.338(91), MSC.343(91), MSC.344(91)

Dear All,

Maritime Lloyd, had revised the technical working procedures as per IMO Resolutions MSC.338(91), MSC.343(91), MSC.344(91) "Amendments to the SOLAS 74 Convention", which amendments are entering in force starting from 01.07.2014. Please note that after 01.07.2014 vessels which are passing Initial/Renewal survey and are subject for issuance of Provisional certificates should be provided with the new forms of certificates. For passenger ships, which are passing Initial/Renewal survey, the surveyor should use new form of survey report. Kindly find below List of procedures which had been revised as well the Survey Reports and Certificates:

1. ML-TWP-ST-002 , Safety Construction Survey
- Provisional Safety Construction Certificate
2. ML-TWP-ST-003 , Safety Equipment Survey;
- Provisional Safety Equipment Certificate
- FORM E
3. ML-TWP-ST-012, Safety Radio Survey;
- Provisional Safety Radio Certificate
- FORM R
4. ML-TWP-ST-019, Passenger Ship Safety Survey.
- Provisional Passenger Ship Safety Certificate
- FORM P
- Initial/Renewal survey report.

Kindly find attached abovementioned revised templates.

Kindly confirm the understanding of the Circular and receipt of amended templates by signing the corresponding form attached.

Best Regards,

Ellen Rukhadze

Chief Executive Officer

Maritime Lloyd

