



# MARITIME LLOYD

34 A, Off.3, Dimitry Tavaddebuli Str, Batumi 6000, Georgia

Tel: + 995 222 77537 ; Fax: + 995 222 77536.

E-mail: [info@geolloyd.com](mailto:info@geolloyd.com), [www.geolloyd.com](http://www.geolloyd.com)

## ***Circular No: 01 /01.01.2011***

**To : Maritime Lloyd Authorized Surveyors  
Managers /Owners of vessels under Maritime Lloyd supervision.**

**Dated: 01.01.2011**

**Subject: The superstitution of BC CODE by new IMSBC CODE  
RESOLUTION MSC.268(85)**

Kindly be informed, that in accordance with the Resolution MSC. 268 (85), the new IMSBC Code supersedes BC Code. The Mandatory application is from 01.01.2011. In the attachment to this Circular, kindly find the corresponding resolution and the amended template of the new Form on the Statutory Certificate.

Kindly confirm the understanding of the Circular by signing the corresponding form attached.

Best Regards,

Ellen Rukhadze

Chief Executive Officer

Maritime Lloyd

